



Cable Modem

[Status](#) [Signal](#) [Addresses](#) [Configuration](#) [Logs](#)

[Open Source](#) [Help](#)

This page displays detailed information intended for use by an authorized Motorola Corporation Cable Modem technician.

Time	Priority	Code	Message
Oct 19 2015 07:44:30	3-Critical	R02.0	No Ranging Response received - T3 time-out;CM- MAC=3c:36:e4:97:00:5c; CMTS-MAC=00:01:5c:69:4c:6d; CM-QOS=1.1;CM-VER=3.0;
Oct 19 2015 07:44:29	6-Notice	I401.0	TLV-11 - unrecognized OID;CM- MAC=3c:36:e4:97:00:5c; CMTS-MAC=00:01:5c:69:4c:6d; CM-QOS=1.1;CM-VER=3.0;
Oct 19 2015 07:44:29	5-Warning	Z00.0	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=- 1;CM-MAC=3c:36:e4:97:00:5c; CMTS-MAC=00:01:5c:69:4c:6d; CM-QOS=1.1;CM-VER=3.0;
Jan 01 1970 00:00:21	3-Critical	R02.0	No Ranging Response received - T3 time-out;CM- MAC=3c:36:e4:97:00:5c; CMTS-MAC=00:01:5c:69:4c:6d; CM-QOS=1.1;CM-VER=3.0;
Jan 01 1970 00:00:15	6-Notice	N/A	Cable Modem Reboot due to power reset ;CM-MAC=3c:36:e4:97:00:5c; CMTS-MAC=00:00:00:00:00:00; CM-QOS=1.1;CM-VER=3.0;
Oct 19 2015 07:41:15	3-Critical	R02.0	No Ranging Response received - T3 time-out;CM- MAC=3c:36:e4:97:00:5c; CMTS-MAC=00:01:5c:69:4c:6d;